

ТАБЛИЦА 4

Статическое давление	Расход (м³/ч) / Nном (кВт)						
	040	045	050	056	063	071	080
	2 полюса						
600 Па	2270/1,1 2730/1,5 3550/2,2 3800/3	1980/1,1 2930/1,5 3560/2,2 7620/3 6300/4 7710/5,5	2230/1,1 3640/1,5 4530/2,2 5420/3 10700/4 12900/5,5 14900/7,5	3850/1,5 6110/2,2 8230/3 8800/4 9800/5,5 10600/7,5	5040/2,2 8600/3 12200/4 17100/5,5 20900/7,5 27000/11 32100/15 34400/18,5	10200/3 13100/4 18100/5,5 23300/7,5 29900/11 37500/15 40100/18,5 41800/22 48600/30	22600/7,5 32000/11 43600/15 48400/18,5 53100/22 61300/30
700 Па	1920/1,1 2340/1,5 3000/2,2 3300/3	1440/1,1 2270/1,5 2860/2,2 4700/3 5450/4 6980/5,5	1500/1,1 2740/1,5 3480/2,2 4610/3 9340/4 11300/5,5 13800/7,5	2730/1,5 4310/2,2 6020/3 6870/4 8200/5,5 9240/7,5	2570/2,2 5420/3 8000/4 13200/5,5 19400/7,5 25800/11 30700/15 33300/18,5	7200/3 8970/4 14000/5,5 20200/7,5 28300/11 35900/15 38400/18,5 40800/22 47400/30	20900/7,5 30200/11 41800/15 46600/18,5 51100/22 59200/30
800 Па	1600/1,1 2000/1,5 2500/2,2 2800/3	893/1,1 1740/1,5 2220/2,2 4080/3 4830/4 5510/5,5	2080/1,5 2810/2,2 3760/3 5950/4 7140/5,5 9100/7,5	1760/1,5 3400/2,2 4800/3 5870/4 7270/5,5 8100/7,5	2900/3 5200/4 9400/5,5 17700/7,5 24300/11 29100/15 32000/18,5	5000/3 5680/4 10000/5,5 14800/7,5 26600/11 34200/15 36500/18,5 39500/22 46000/30	19000/7,5 28100/11 39800/15 44600/18,5 49200/22 57100/30
900 Па	1270/1,1 1650/1,5 2080/2,2 2350/3	1230/1,5 1590/2,2 3620/3 4260/4 4870/5,5	1400/1,5 2150/2,2 2900/3 5230/4 6260/5,5 7030/7,5	2580/2,2 4020/3 4880/4 6330/5,5 6940/7,5	2700/4 7700/5,5 15600/7,5 22700/11 27400/15 30800/18,5	3200/3 2710/4 7500/5,5 11600/7,5 24300/11 32300/15 34600/18,5 38100/22 44400/30	16900/7,5 25700/11 37600/15 42400/18,5 46900/22 54900/30

часть II (давление от 600Па)

Расход (м³/ч) / Пном (кВт)						Статическое давление
080	090	100	112	125		
4 полюса					6 полюсов	
4220/2,2 6000/3 7690/4 8450/5,5 9380/7,5 12100/11 14900/15	8600/4 12700/5,5 16800/7,5 16900/11 19100/15 30500/18,5	7800/4 13600/5,5 16300/7,5 23000/11 28100/15 31600/18,5 38500/22 58300/30	11200/5,5 12100/7,5 33600/11 47000/15 53400/18,5 59600/22 69200/30 74700/37	30500/11 39600/15 47100/18,5 54400/22 70900/30 90400/37 92100/45	11800/11 16300/15 18300/18,5	600 Па
4450/5,5 5320/7,5 8350/11 11900/15	4900/4 8790/5,5 10400/7,5 9800/11 11500/15 20300/18,5	3100/4 8120/5,5 10800/7,5 16400/11 20900/15 25400/18,5 30300/22 44400/30	4700/5,5 3140/7,5 25300/11 35700/15 39400/18,5 43200/22 55100/30 58000/37	22600/11 30100/15 36100/18,5 41600/22 65000/30 84200/37 73400/45		700 Па
4650/11 8620/15	4700/5,5 4600/7,5 3300/11 4600/15 13400/18,5	2560/5,5 5000/7,5 8600/11 12700/15 17200/18,5 24100/22 32800/30	19100/11 27400/15 30600/18,5 33700/22 41000/30 42100/37	14500/11 22000/15 27600/18,5 32500/22 59000/30 76300/37 67500/45		800 Па
5190/15	7900/18,5	3970/15 6300/18,5 17500/22 26800/30	13600/11 21300/15 24200/18,5 27400/22 33700/30 35000/37	4520/11 12800/15 18400/18,5 23300/22 49900/30 64500/37 59400/45		900 Па