

ТАБЛИЦА 4 БЫСТРОГО ВЫБОРА УСТАНОВОК ВКОП 0

Статическое давление	Расход (м³/ч) / Нном (кВт)						
	040	045	050	056	063	071	080
	2 полюса						
<b>100 Па</b>	5500/1,1 6500/1,5 8500/2,2 9260/3	7710/1,1 9180/1,5 10700/2,2 11700/3 14200/4 15800/5,5	8940/1,1 11000/1,5 12400/2,2 14500/3 14800/4 17200/5,5 18300/7,5	12200/1,5 15100/2,2 17500/3 19500/4 21900/5,5 23600/7,5	15900/2,2 19900/3 23200/4 26700/5,5 26300/7,5 32700/11 37800/15 38900/18,5	22300/3 26200/4 28900/5,5 34400/7,5 36600/11 44100/15 47000/18,5 46600/22 53800/30	29500/7,5 39100/11 51000/15 55900/18,5 60700/22 70200/30
<b>150 Па</b>	5300/1,1 6340/1,5 8250/2,2 8960/3	7300/1,1 8770/1,5 10200/2,2 11400/3 13900/4 15400/5,5	8460/1,1 10500/1,5 11900/2,2 14000/3 14500/4 16900/5,5 18000/7,5	11600/1,5 14500/2,2 16900/3 18800/4 21200/5,5 22900/7,5	15100/2,2 19200/3 22400/4 26000/5,5 25900/7,5 32200/11 37300/15 38400/18,5	21400/3 25300/4 28100/5,5 33500/7,5 36000/11 43400/15 46400/18,5 46200/22 53300/30	28700/7,5 38400/11 50300/15 55300/18,5 60000/22 69400/30
<b>200 Па</b>	5100/1,1 6100/1,5 7950/2,2 8660/3	6870/1,1 8340/1,5 9740/2,2 11100/3 13500/4 14900/5,5	7930/1,1 9980/1,5 11400/2,2 13400/3 14200/4 16500/5,5 17700/7,5	11000/1,5 13800/2,2 16200/3 18100/4 20400/5,5 22100/7,5	14300/2,2 18400/3 21600/4 25200/5,5 25400/7,5 31700/11 36800/15 38000/18,5	20500/3 24400/4 27100/5,5 32600/7,5 35500/11 42700/15 45800/18,5 45700/22 52900/30	28100/7,5 37700/11 49600/15 54600/18,5 59400/22 68700/30
<b>250 Па</b>	4900/1,1 5860/1,5 7660/2,2 8280/3	6390/1,1 7820/1,5 9250/2,2 10800/3 13100/4 14500/5,5	7360/1,1 9400/1,5 10800/2,2 12800/3 13800/4 16100/5,5 17400/7,5	10400/1,5 13200/2,2 15500/3 17400/4 19700/5,5 21300/7,5	13500/2,2 17500/3 20800/4 24300/5,5 24900/7,5 31200/11 36400/15 37600/18,5	19500/3 23200/4 26100/5,5 31500/7,5 34900/11 42100/15 45100/18,5 45200/22 52400/30	27400/7,5 37000/11 48900/15 53900/18,5 58700/22 67800/30
<b>300 Па</b>	4620/1,1 5600/1,5 7280/2,2 7840/3	5840/1,1 7260/1,5 8630/2,2 10500/3 12600/4 13900/5,5	6750/1,1 8800/1,5 10200/2,2 12000/3 13500/4 15700/5,5 17100/7,5	9680/1,5 12500/2,2 14700/3 16600/4 19000/5,5 20400/7,5	12600/2,2 16500/3 19900/4 23400/5,5 24400/7,5 30600/11 35900/15 37200/18,5	18500/3 22100/4 25100/5,5 30600/7,5 34200/11 41400/15 44500/18,5 44800/22 51900/30	26900/7,5 36300/11 48200/15 53200/18,5 58000/22 67000/30
<b>350 Па</b>	4300/1,1 5260/1,5 6870/2,2 7180/3	5220/1,1 6640/1,5 7950/2,2 10100/3 12200/4 13400/5,5	6070/1,1 8170/1,5 9480/2,2 11300/3 13100/4 15300/5,5 16800/7,5	8970/1,5 11800/2,2 13900/3 15800/4 18200/5,5 19400/7,5	11400/2,2 15700/3 18900/4 22400/5,5 23900/7,5 30100/11 35200/15 36800/18,5	17300/3 20900/4 24100/5,5 29500/7,5 33600/11 40800/15 43800/18,5 44300/22 51400/30	26200/7,5 35700/11 47500/15 52400/18,5 57400/22 66200/30
<b>400 Па</b>	3960/1,1 4900/1,5 6430/2,2 6580/3	4510/1,1 5980/1,5 7040/2,2 9730/3 11800/4 12700/5,5	5260/1,1 7480/1,5 8680/2,2 10500/3 12600/4 14900/5,5 16400/7,5	8210/1,5 11000/2,2 13100/3 15000/4 17300/5,5 18100/7,5	10100/2,2 14700/3 17800/4 21500/5,5 23400/7,5 29600/11 34700/15 36400/18,5	16100/3 19700/4 22900/5,5 28400/7,5 32900/11 40200/15 43100/18,5 43900/22 51000/30	25500/7,5 35000/11 46800/15 51700/18,5 56500/22 65200/30
<b>500 Па</b>	2730/1,1 4150/1,5 4120/2,2 4300/3	2800/1,1 4090/1,5 4500/2,2 8770/3 10300/4 10900/5,5	3250/1,1 5470/1,5 6890/2,2 7660/3 11700/4 14000/5,5 15700/7,5	5900/1,5 9190/2,2 11200/3 13000/4 15300/5,5 14400/7,5	7720/2,2 12100/3 15300/4 19400/5,5 22200/7,5 28400/11 33500/15 35400/18,5	13400/3 16900/4 20700/5,5 25900/7,5 31400/11 39000/15 41800/18,5 42800/22 49800/30	24200/7,5 33500/11 45300/15 50100/18,5 54800/22 63200/30

## часть I (давление до 500Па)

Расход (м³/ч) / Нном (кВт)						Статическое давление
080	090	100	112	125		
4 полюса				6 полюсов		
24000/2,2 28700/3 28800/4 34300/5,5 39600/7,5 43700/11 41800/15	35500/4 42400/5,5 46000/7,5 51600/11 58000/15 61600/18,5	35600/4 45800/5,5 50700/7,5 57100/11 67900/15 76000/18,5 73700/22 76200/30	50800/5,5 57400/7,5 58000/11 72100/15 78200/18,5 84400/22 95600/30 109000/37	64100/11 73600/15 82200/18,5 91800/22 107000/30 110000/37 123000/45	38900/4 49500/5,5 61900/7,5 70200/11 84100/15 96600/18,5	100 Па
22900/2,2 27100/3 27600/4 33200/5,5 38000/7,5 42400/11 40800/15	33600/4 40600/5,5 44400/7,5 50000/11 56300/15 60000/18,5	33500/4 43700/5,5 48500/7,5 55200/11 66000/15 73800/18,5 72100/22 74800/30	47600/5,5 54500/7,5 56300/11 70400/15 76400/18,5 82600/22 93600/30 108000/37	62000/11 71500/15 80100/18,5 89500/22 105000/30 108000/37 121000/45	34900/4 45100/5,5 56900/7,5 67600/11 81100/15 93100/18,5	
21200/2,2 25400/3 26300/4 31700/5,5 36400/7,5 40700/11 39500/15	31400/4 38600/5,5 42700/7,5 48200/11 54400/15 58200/18,5	31300/4 41500/5,5 46200/7,5 53300/11 64100/15 71400/18,5 70500/22 73400/30	44300/5,5 51400/7,5 54500/11 68400/15 74500/18,5 80500/22 91800/30 106000/37	59600/11 69300/15 77800/18,5 86900/22 103000/30 106000/37 118000/45	30000/4 39200/5,5 50700/7,5 64800/11 77700/15 89600/18,5	200 Па
19200/2,2 23400/3 25100/4 30200/5,5 34500/7,5 39100/11 38200/15	28900/4 36400/5,5 40900/7,5 46300/11 52500/15 56400/18,5	29000/4 38800/5,5 43600/7,5 51300/11 62200/15 68800/18,5 68600/22 71900/30	40800/5,5 47900/7,5 52700/11 66400/15 72300/18,5 78500/22 90100/30 103000/37	57100/11 66900/15 75400/18,5 84200/22 101000/30 105000/37 116000/45	23000/4 31300/5,5 42500/7,5 61200/11 73500/15 84800/18,5	
16300/2,2 20900/3 23700/4 28800/5,5 32600/7,5 37300/11 36700/15	25700/4 33700/5,5 38800/7,5 44100/11 50100/15 54400/18,5	26200/4 36200/5,5 40700/7,5 49100/11 59700/15 66100/18,5 66800/22 70300/30	36900/5,5 44000/7,5 50800/11 64300/15 70400/18,5 76400/22 88100/30 100000/37	54500/11 64200/15 72900/18,5 81300/22 98800/30 103000/37 113000/45	16200/4 23100/5,5 32100/7,5 57000/11 68700/15 79200/18,5	300 Па
11700/2,2 13900/3 21800/4 26900/5,5 30700/7,5 35200/11 35200/15	20900/4 29800/5,5 36800/7,5 41700/11 47300/15 52300/18,5	22900/4 33000/5,5 37500/7,5 46200/11 56700/15 63200/18,5 64800/22 68800/30	32200/5,5 39400/7,5 48700/11 62000/15 68000/18,5 74200/22 86200/30 96500/37	51600/11 61100/15 69500/18,5 77900/22 96400/30 101000/37 111000/45	10500/4 16400/5,5 24100/7,5 51100/11 63100/15 71200/18,5	
9600/2,2 11600/3 19100/4 24500/5,5 28300/7,5 32500/11 33500/15	16500/4 20900/5,5 34700/7,5 38900/11 44100/15 50000/18,5	18100/4 28900/5,5 33100/7,5 42900/11 53400/15 59500/18,5 62500/22 67200/30	26300/5,5 34000/7,5 46500/11 59800/15 65700/18,5 71800/22 83700/30 92800/37	48500/11 57700/15 65900/18,5 74300/22 93800/30 99500/37 108000/45	3000/4 9200/5,5 17400/7,5 42100/11 53500/15 53600/18,5	400 Па
6570/2,2 8690/3 10800/4 11700/5,5 13100/7,5 16000/11 28900/15	12300/4 16100/5,5 24100/7,5 25900/11 28800/15 43500/18,5	12500/4 18800/5,5 21700/7,5 30300/11 37500/15 38000/18,5 57300/22 63600/30	17700/5,5 20700/7,5 41000/11 54500/15 60400/18,5 66400/22 77400/30 85300/37	40800/11 50100/15 57700/18,5 65500/22 88000/30 95400/37 101000/45	3600/7,5 25700/11 31100/15 34400/18,5	